



問題集

http://www.ktest.jp 1年で無料進級することに提供する Exam: SVC-16A

Title : Apple Service

Fundamentals

Version: Demo

- 1. What color indicates that the Liquid Contact Indicators inside a MacBook Pro (13-inch, Mid 2012, have been triggered?
- A. Red
- B. Blue
- C. White
- D. Yellow

Answer: A

- 2. What is the likely cause of an iMac (21.5-inch, Late 2013) producing a single error tone at startup that repeats every five seconds.
- A. The unit does not have RAM or RAM is not installed properly.
- B. The logic board has failed and must be replaced.
- C. The RAM does not pass data integrity tests.
- D. The hard drive has failed S.M.A.R.T. status.

Answer: A

- 3. Apple recommends a DIMM installation scheme for the Mac Pro (Late 2013) that:
- A. Increases processing power
- B. Enhances graphics processing
- C. Optimizes system cooling
- D. Enables use of special memory modules

Answer: D